Potential Significance to Water Resources & Drainage Structure Condition Index

NOTHGATE TO SUMMIT

Potential Road and Trail Impacts To Water Resources

- High
- Medium
- Low

Drainage Structure Condition Index

Higher Score = poor condition of structure

- Low
- Medium
- High

- Park Roads / Trails with No Significant Impacts to Water Resources
- Local Roads
- Paved Park Roads

- Museum/Visitor center
- Campground
- Group Camp
- Horse Camp
- Mt Diablo State Park
- CSP Lands Operated by EBRPD
- Other Public Lands

Public Access Limits

- No Access
- Restricted Access
- Intermittent Stream

Map Page Location



Scale
1:27,257
1 inch = 2,271 feet

N

Miles
0 0.1 0.2 0.3 0.4 0.5

Mount Diablo State Park Road and Trail Management Plan

NOTES:

Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

FACILITIES MANAGEMENT DIVISION

Date: 1/28/2015
Sources:
Calif. Dept. of Parks & Recreation
Calif. Geologic Survey Road and Trail Inventory
Other Public Lands: GreenInfo, Inc.

CALIFORNIA STATE PARKS SINCE 1864