




### Building & Maintaining the San Clemente Beach Trail

- Challenges of Construction & Maintenance
  - Constraints of a narrow right-of-way
  - Working around and with an Active Railroad
  - Vandalism
  - Maintaining Public Access
  - Signage
  - Policies & Ordinances
  - Maintenance & Public Access





**Active RR**

- RR Shut down
- Night work



**Active RR**

- Safety Concerns
- Added Expense



- Phasing

09/15/2006




**Access**

- Public Access
- Perception of Access



- Public Access
- No Alternate Rte



- High Use Trail
- Multi-Use
  - Pedestrian
  - Bicyclists
  - Strollers
  - Dog Walkers

