



# Potential Significance to Water Resources & Drainage Structure Condition Index

## MITCHELL CANYON TO SUMMIT

**Potential Road and Trail Impacts To Water Resources**

- High
- Medium
- Low

**Drainage Structure Condition Index**  
Higher Score = poor condition of structure

- Low
- Medium
- High

— Park Roads / Trails with No Significant Impact to Water Resources  
— Local Roads  
— Paved Park Roads

Museum/Visitor center  
 Campground  
 Mt Diablo State Park  
 Other Public Lands  
 Public Access Limits  
 No Access  
 Intermittent Stream

Map Page Location

Scale  
1:22,772  
1 inch = 1,898 feet

## Mount Diablo State Park Road and Trail Management Plan

**NOTES:**  
Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

<p><b>FACILITIES MANAGEMENT DIVISION</b></p>	<p>Date: 1/27/2015 Sources: Calif. Dept. of Parks &amp; Recreation Calif. Geologic Survey Road and Trail Inventory Other Public Lands: GreenInfo, Inc.</p>	
--	--	--