Potential Significance to Water Resources & Drainage Structure Condition Index

SOUTHGATE TO SUMMIT

Potential Significance To Water Resources
- High
- Medium
- Low

Drainage Structure Condition Index
Higher Score=poor condition of structure
- Low
- Medium
- High

- Park Roads / Trails with No Significant Impact to Water Resources
- Local Rds
- Paved Park Roads

- Museum/Visitor center
- Campground
- Group Camp
- Horse Camp
- Mt Diablo State Park
- Intermittent Stream

Map Page Location



Scale
1:24,000
1 inch = 2,000 feet
N
Miles
0 0.1 0.2 0.3 0.4 0.5

Mount Diablo State Park
Road and Trail Management Plan

NOTES:
Parcel boundaries are approximate and should not be considered legal descriptions. Maps are intended for study purposes only.

FACILITIES MANAGEMENT DIVISION

Date: 1/28/2015
Sources:
Calif. Dept. of Parks & Recreation
Calif. Geologic Survey
Road and Trail Inventory
Other Public Lands:
GreenInfo, Inc.

CALIFORNIA STATE PARKS SINCE 1864